

## Summary

- We are continuing to maintain and upgrade the telescope sub systems
- We are seeing higher rate of failure from aging of parts and human errors


## Maintenance & Upgrade

- Recovery from water leak
- Insertion of leap second
- Maintenance of M1 actuators
- Replacement of electrical parts
- Monitor of rubber springs

- Measurement of vibrations
- Replacement of IR suppression mirrors
- Adjustment of LGRs

- Commissioning of POpt2/HSC
- Upgrade of LCUs











TIME CODE GENERATOR TRANSLATOR TXC-101DTR-6D




GPS MODE SYNC LOCK +LEAP UTC 12Y139D22H17M02S FRI -000.843ms

## Inserted leap second

TIME CODE INTERFACE
















## Upgraded FRCU

#### **TCFRCU**









#### TCADCU







## TCADCU






TCFRCU

TOADOLL





### **Troubles**



## Troubles from aging

- Loose control of TUE UL θ axis
- Angle offset of NsOpt ImR
- Loose connections on spider connectors
- Problem in moving AGSH shutters
- Water leak in NsIR AGSH prove

- Short circuit and cut on electrical wires
- Faulty sensors
- Warmer coolant from Chiller A
- Cooling problem on NsOpt SV
- ...

# Troubles from human errors and unknown reasons

- Broke mechanisms on TUE UL
- Trouble in using AO188 with NsOpt M2
- Broke driver mechanism on air dumper on great wall

- Broken He hoses on Cs InR
- Oil leak from Cs ADC
- Trouble in rotating Cs
  ADC
- Intermittent fault from Acturator 8-29
- Black out in the dome
- ...

